


ESTANTERÍA BAJA NORDIK

ATENCIÓN AL CLIENTE
964 321 111

Web: www.mueblespitarch.com
e-mail: comercial@mueblespitarch.com





Las herramientas que necesitas (no incluidas)




Los herrajes que encontrarás en el kit

Col x 2 Nº721060 	Exc x 4 Nº721016/721017 	Tap x 8 Nº721308 	Aut x 4 Nº721002
Pat x 4 Nº710186 	Lz x 1 Nº721034 	Tam x 2 Nº721508 	Tpt x 16 Nº721070
Moldgr x 1 Nº710167 	Moldpq x 2 Nº710160 	Cesta x 2 Nº710176 	




REF. 606
LOTE 5138


Las piezas incluidas en el kit



Tapa
672x311 mm
60231




Suelo
670x311 mm
60232



Lateral izqdo
664x310 mm
60615



Lateral drcho
664x310 mm
60614



Balda
636x309 mm
60220



Pieza vertical larga
338x308 mm
60253



Pieza vertical corta
310x308 mm
60252

Te aconsejamos

Ordena y
cuenta las piezas
y herrajes



Habilita una
zona para
el montaje

No fuerces los
tornillos y los elementos
de montaje

Sigue paso a paso
las instrucciones
de montaje

1

El primer paso es el montaje de los herrajes



1

El primer paso es el montaje de los herrajes

Col x 2

Tap x 4

Tam x 2

Los mechones “Tap” se utilizan para el ensamblado tanto del techo como del suelo

Diagram illustrating the application of glue (COLA) and taps (Tap) to panels 6 and 7. Panel 6 is shown with two taps (3 cms) and two tubes of glue. Panel 7 is shown with four taps (3 cms) and two tubes of glue. The taps are used for assembly both of the ceiling and the floor.

Exc x 4

Diagram illustrating the application of glue (COLA) and taps (Tap) to panel 5. Panel 5 is shown with four taps (3 cms) and two tubes of glue. The taps are used for assembly both of the ceiling and the floor.

2

Col x 1

Diagram illustrating the assembly of panels 5, 6, and 7. Panel 6 is shown being attached to panel 5. Panel 7 is shown being attached to panel 5. The panels are joined using glue (COLA) and taps (Tap).

3

Lz x 1

Diagram illustrating the assembly of panels 1, 2, and 3. Panel 2 is shown being attached to panel 1. Panel 3 is shown being attached to panel 1. The panels are joined using glue (COLA) and taps (Tap). A note indicates "Girar 180°" (Turn 180°) and "Lz" (Lz).

3

Col x 1

Lz x 1

Aut x 4

Pat x 4

Tpt x 16

Diagram illustrating the assembly of panels 1, 2, 3, and 4. Panel 4 is shown being attached to panel 1. Panel 2 is shown being attached to panel 1. Panel 3 is shown being attached to panel 1. The panels are joined using glue (COLA) and taps (Tap). A note indicates "Girar 180°" (Turn 180°) and "Lz" (Lz).

4

Col x 1

Moldgr x 1

Moldpq x 2

Cesta x 2

Cinta americana

Precintar las molduras hasta que seque la cola (aprox. 3 horas)

Diagram illustrating the assembly of panels 1, 2, 3, and 4. Panel 4 is shown being attached to panel 1. Panel 2 is shown being attached to panel 1. Panel 3 is shown being attached to panel 1. The panels are joined using glue (COLA) and taps (Tap). A note indicates "Girar 180°" (Turn 180°) and "Lz" (Lz).