





1	General information	Supplier's name or trade mark	INSPIRE
2		Supplier's address	ADEO Services, 135 rue Sadi Carnot - CS0001, 59790 RONCHIN
3		Model Identifier - Luminaire Supplier reference	C806
4		Light sources maker model	C806

Instructions on how to remove lighting control parts and/or non-lighting parts, if any, or how to switch them off or minimise their power consumption during light source testing

	Explanation of the step	Pictures	Tools
Step 1	Remove the glass from lamp base by hand		/
Step 2	Remove the blue / brown wires from the terminal block by pressing the terminal block		/
Step 3	Remove the screw on the back of lamp base with a screwdriver	 	screwdriver
Step 4	Remove the screw on the LED lens with a screwdriver	 	screwdriver
Step 5	Release the LED board by removing the clasps		/
Step 6	Remove the sleeves and separate the lens from the LED board		/
Step 7	Remove the glue from the weld point with a knife	 	knife
Step 8	Remove the wire with a soldering iron	 	Soldering Iron