

LIGHT SOURCE REMOVING INSTRUCTION

Creation date (dd/mm/yyyy) :




21-Jan-22

Last update date (dd/mm/yyyy) :

03-19-22

1	General information	Supplier's name or trade mark	NO NAME
2		Supplier's address	ADEO Services, 135 rue Sadi Carnot - CS0001, 59790 RONCHIN
3		Model Identifier - Luminaire Supplier reference	F7110WV4
4		Light sources maker model	HT9318-06-4000K

Instructions on how to remove lighting control parts and/or non-lighting parts, if any, or how to switch them off or minimise their power consumption during light source testing

	Explanation of the step	Pictures	Tools
Step 1	REMOVE THE END CAP		NA
Step 2	TURN THE LED TUBE 90°,		NA
Step 3	take down the LED tube		NA
Step 4			
Step 5			
Step 6			
Step 7			
Step 8			

	Step 9			
	Step 10			