


12ID2-25.1A



| n° | Description                       | n° | Description                              | n° | Description                   | n° | Description            |
|----|-----------------------------------|----|--|----|-------------------------------|----|------------------------|
| 1  | Screw M5X22 T type                | 15 | (No.21) Torque spring                    | 29 | Motor                         | 43 | Magnetic ring 9X5.2X12 |
| 2  | Chuck                             | 16 | Gasket for torque sleeve                 | 30 | Back cover                    | 44 | Tube battery pack      |
| 3  | Head shell                        | 17 | Block                                    | 31 | Push rod                      | 45 | Heat shrinkable tube   |
| 4  | Torque sleeve                     | 18 | Reset spring (Gearbox No. 40)            | 32 | Transparent lampshade         | 46 | L shape Battery pack   |
| 5  | Adjusting ring                    | 19 | Round pin                                | 33 | Lampshade for Power indicator | 47 | Charger                |
| 6  | Adjusting inner ring              | 20 | Steel ball                               | 34 | No.10 Elastic steel wire      |    |                        |
| 7  | Screw ST3*14(T type)              | 21 | Gearbox housing (with inserts) + bushing | 35 | Speed adjustment button       |    |                        |
| 8  | Cover plate                       | 22 | Inner ring side pin                      | 36 | Housing                       |    |                        |
| 9  | No 12 Tuning fork                 | 23 | Shift gear steel wire -7                 | 37 | Right decorative part         |    |                        |
| 10 | Pressing plate                    | 24 | Self-lock pin                            | 38 | Switch assembly               |    |                        |
| 11 | No. 30 powder metallurgy assembly | 25 | Gasket                                   | 39 | Left arrow                    |    |                        |
| 12 | Deep groove ball bearing          | 26 | Big gasket                               | 40 | Right arrow                   |    |                        |
| 13 | Output shaft                      | 27 | Mechanical screw M3X6                    | 41 | Left decorative part          |    |                        |
| 14 | Internal thread                   | 28 | Motor end cap                            | 42 | Metal card                    |    |                        |