

---

## Digital Luggage Scale User's Manual

Thank you for choosing our luggage scale. This digital luggage scale has the following characteristics: precision weighing, attractive design, easy to carry, durability and more. It is perfect for travel, family use, shopping or outdoor activities. Please read this manual carefully to ensure correct operation of the scale.

### **SPECIFICATIONS:**

- Equipped with High Precision Strain Gauge Sensor System
- Maximum Capacity: 50 kg/110 lb
- Minimum Capacity: 50 g/0.02 lb
- Division: 10 g/0.02 lb
- Unit: kg/lb
- One Button
- Power: 1 Lithium Battery (Cr2032)

### **Battery Instructions:**

1. Remove battery holder. Place one 3v battery in the holder according to image below and insert battery holder into scale.
2. LCD displays "18888". within 3 seconds the scale the LCD displaying "0.0kg"

### **Scale Operation:**

1. Press the POWER button to turn on scale. The LCD displays "18888" at startup. After startup be sure to hold the scale in a vertical state (within 3 seconds) and the LCD display reads "0.0 kg"
2. The article to be weighed should be attached to the scale while the LCD displays "0.0 kg". Next grip the scale handle and lift up the article. The LCD will display the article weight along with an "H" in the lower left corner.
3. To reset the scale and weigh another article, remove article from scale, then press and release POWER button. LCD will display "0.0 kg".
4. Press POWER within 3 seconds button to turn scale off or scale will power off automatically after 60 seconds.

---

### **Unit Transition (kg/lb):**

1. Press the button to turn on scale. The LCD displays " 0.00kg " at startup. While LCD displays " 0.00kg ", press button to change scale weighing unit to lb or kg.

### **TARE Function: (Using container to weigh item)**

1. When you use a container to weigh an article, weigh the container by itself first. The LCD displays container weight with "H" in lower left corner, continue to lift container, press and release POWER button to reset scale to (0.0).

2. Place article to be weighed in container and weigh with scale. Article weight only will be displayed.

### **POWER Button function:**

1. Turn unit on/off
2. Reset to zero
3. Activate "TARE"
4. Mode Change kg/lb while LCD displays 18888.

### **Usage Notes:**

1. The maximum weight limit for this scale is 50KG. If weights greater than 50KG are placed on the scale, the display shows "ERR". Moreover, attempting to weigh items over 50KG could damage the scale.
2. When the LCD displays the "Battery Symbol", it means that the battery is low. Please change the battery as soon as possible.
3. To ensure the highest accuracy possible, avoid shaking or rocking while weighing items with the scale.