






















M938






№		PCS			
			mm	mm	mm
1		3		1180	1900
2		1		60	1660
3		1		380	1900
4		1		380	1900
5		1		770	1801
6		1		770	1801
7		1		238	1180
8		1		124	1170
9		1		238	1180
10		1		124	1170
11		1		1180	1900
12		1			
13		3	60	60	1810
14		1	60	70	420
15		1	60	70	410
16		3	40	60	410
17		2	40	60	1530
18		1	40	60	420
19		2	40	120	1180
20		1	10	89	670
20.1		1	10	89	690
21		1	10	89	1180
22		2	10	192	1579
23		2	10	192	883
24		3	10	152	1180
25		1	10	152	897
26		1	10	152	897
27		1	10	152	872
27.1		1	10	152	892
28		2	10	152	399
29		1	60	82	1839
30		1	60	82	1839
31		1	60	82	1688
32		2	40	120	1620
33		3	40	120	1335

34		3	40	120	1219
35		2	40	120	934
36		12	40	120	252
37		2	12	1179	1900
38		2	12	575	1179
39		2	12	271	1579
40		2	12	271	896
41		3	13	92	1890
42		3	13	92	1887
43		2	13	92	1899
44		2	13	92	228
45		4			1660
46		3			1250
47		3			1250
48		3 pack			
49		3		1m	3.33m
50		2			
51		2			
52		10			
52.1		2			
53		12			
54		6			
54.1		6			
55		1			
56		1			
57		1			
58		1	T25		
59		1	T20		
60		1	T15		
61		1			
62		1			746
63		1			756


M938G




Don't use !!!

№		PCS			
			mm	mm	mm
1g		2		1172	1910
2g		2		1172	594
3g		1	60	60	1880
4g		1	60	60	584
5g		1	30	57	1600
6g		2	60	60	584
7g		1			10m
C	 4x50	36			



1A



1B




6g




C x12


2



3





4




5



$$x=y$$




Det A




Det C






Det B






Det D



6




C x4





G x6

7






E x16




E x16

53



Not included

8





$H \times 40$

34

36

$b \times 3$







$a \times 2$










35

33



9








E x32


$$x = y$$




E x 48




53











A_{x4}







15





26




Paint


27





16





E x 18




Paint








C x8



Interior view



19

14-19mm

54

57


54.1


57

14-19mm

6

5






55


D x3

1



55


2



D x2

56

3



21

Int.

61

D x4

Int.


Ø12





III


D x10

63

62

















42

D x24












47



F

MAX
120 kg/m²



M938S



№		PCS			
			mm	mm	mm
1S		2		1180	1900
2S		2	12	343	1180
3S		2	60	60	1810
A	 4x70	18			
B	 4x100	2			
C	 4x50	20			

27

