






YS-264



Order	(L*W) MM
①	520*445=1
②	520*445=1
③	505*445=1
④	1170*78=1
⑤	1170*78=2
⑥	1170*60=2
⑦	599*230=1
⑧	599*230=1
⑨	209*84=2
⑩	209*84=2
⑪	558*283=2
⑫	599*230=1
⑬	599*230=1
⑭	558*84=2
⑮	558*283=2




A




∅15*13mm
=24

V




∅8*40mm
=24

C




∅8*40mm
=2

F




∅20*0.3mm=24

YG-A004



300*40*40mm
=4

H-H




67*67*40mm
=2

I



4*14mm
=150

J



∅20*8mm
=3

K




∅10*43mm
=3

L




∅6*70mm
=3

W



35*300*107mm
=4

X




25*25*31mm
=4

P




∅18*4mm
=6

U




170*240*87mm
=2

N




∅4*30mm
=4

1




2




C=2* 

3




N=2* 

4




V=4* 


5


 $A=4*$



6


 $N=2*$



7


 $V=20*$


8



 $A=10*$


9




A=10* 

10




H-H=2* 
I=16* 

11




I=7* 

12




I=4* 

13




I=10* 

14




I=4* 

15




I=2* 

16




X=2* 
I=8* 


17


 $I=6^*$



18


 $I=4^*$



19


 $I=4^*$


20



 $I=2^*$


21




$X=2^*$ 
 $I=8^*$ 

22




$G-G=4^*$ 
 $I=24^*$ 


23




24




25




26




27


 $l=8^*$



28




F=24




29




30




31




32



33



OK!



P=6