















Ean code :8424010778360/8424010778377/8424010778384/  
8424010778391/8424010778407/8424010778414/8424010778421  
8424010821929/8424010821936/8424010821943/8424010821950/  
8424010821967/8424010821974/8424010821981





| REF | PARTE | PIEZA                                                                                |                                                                                       | CANT | DIM |
|-----|-------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|------|-----|
|     | A1    |    |    | 1    |     |
|     | A2    |    |    | 1    |     |
|     | A3    |    |    | 1    |     |
|     | A4    |    |    | 1    |     |
|     | A5    |     |    | 1    |     |
|     | A6    |    |    | 1    |     |
|     | B1    |  |  | 1    |     |
|     | B2    |  |  | 1    |     |
|     | B3    |   |                                                                                       | 1    |     |
|     | C1    |  |  | 1    |     |
|     | C2    |  |  | 1    |     |
|     | D     |  |  | 3    |     |
|     | E1    |  |  | 1    |     |
|     | E2    |  |  | 1    |     |
|     | E3    |   |                                                                                       | 1    |     |


| REF | PARTE | PIEZA                                                                                                                                                                  | CANT | DIM |
|-----|-------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----|
|     | F     |    | 128  |     |
|     | G     |   | 4    |     |
|     | H     |                                                                                       | 6    |     |
|     | J     |                                                                                       | 6    |     |
|     | K     |                                                                                       | 1    |     |
|     | L     |                                                                                       | 2    |     |
|     | M1    |                                                                                     | 1    |     |
|     | M2    |                                                                                     | 1    |     |
|     | N1    |                                                                                     | 1    |     |
|     | N2    |                                                                                     | 1    |     |
|     | P     |                                                                                     | 4    |     |
|     | Q     |  M8*20                                                                              | 54+2 |     |
|     | Q1    |  M8*25                                                                              | 20+1 |     |
|     | Q2    |  M6*20                                                                              | 30+2 |     |
|     | Q3    |  M4*18                                                                              | 4    |     |




# PASO 01





PASO1





PASO2





## PASO 02





## PASO 03




## PASO 04



**PASO 05**





# PASO 06





M8\*20

Q (X2)



# PASO 07




# PASO 08



# PASO 09




# PASO 10



M8\*20

Q

X8





M8\*25



Q1

X4

# PASO 11






# PASO 12





|                                                                                     |         |                                                                                     |         |                                                                                     |       |                                                                                       |        |
|-------------------------------------------------------------------------------------|---------|-------------------------------------------------------------------------------------|---------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|--------|
|  | N2 (X1) |  | N1 (X1) |  | M8*20 |  | Q (X2) |
|-------------------------------------------------------------------------------------|---------|-------------------------------------------------------------------------------------|---------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|--------|


# PASO 13



## PASO 14



1





2

Antes de cargar las placas de aluminio F y G, pasar de la figura 1 a la figura 2 con el rocker




R (X1)



## PASO 15




## PASO 16



PASO 17





## PASO 18



M6\*20

Q2 X12

## PASO 19



Q4 X12