




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD,

- 1 - A 960500 NU
- 2 - A 860700 NU
- 3 - A 963298 NU
- 4 - A 961760 XX
- 5 - A 860899 NU
- 6 - A 961649 NU
- 7 - A 860946 XX
- 8 - B 961851 XX
- 8a - B 961858 XX
- 9 - A 963751 NU
- 9a - B 960473 NU
- 10 - A 961168 NU
- 11 - A 961462 NU
- 12 - A 6677 XX




	P	bar		T	°C		MAX. 10		MAX. 80		5			Q (3 bar)
	T	°C		MAX. 80		65			40		29		l/min	29





Ideal Standard

CERABASE


11.2022 / B565280




B D492 ..





A 7392 ..



Ideal Standard International NV
Corporate Village – Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium
<http://www.idealstandardinternational.com>





0,3 MPa

3 bar

			0	1	2	3	4	5	6	7	8	9
			°C	°C	°C	°C	°C	°C	°C	°C	°C	°C
50°C	16°C		49,5	49,5	48	46	42,5	41	37	33,5	31	28
65°C	16°C		65	65	63,5	60,5	57	53,5	49	44,5	39	34,5
81°C	16°C		81	81	78,5	73	69	63,5	56	49	42,5	36