






0 1 2 3 4 5cm




A
x8




B
x8




C
x6




D
x4




E
x4



F
x8




G
x8



J
x3



H1a
x2




H1b
x2




H1c
x12


H
x2



L
x1



K
x2





N
x2



M
x1



I
x2



Ø5
metal

