

**Product identification**

<b>Adeo Ref</b>	844611		
<b>Product EAN</b>	3276000592303		
<b>Supplier ref</b>	SD98905L.04		

**Template version history**

Version	Status	Date Status	Comments
V.0	Under construction	20/08/2018	Template construction

**Object**

In case of supplier cannot provide related documents on time, or the document is not necessary to provide as confirmed by ADEO QM, supplier could use the missing documents template to replace required document.

**Name and address of Supplier:**

Zhejiang Suerda Sanitary CO.,LTD.  
 Yuhuan Sci-tech Industrial Area  
 Qinggang Town(xiaqiu),Yuhuan,Zhejiang,China  
[Tel:0086 576 89916101](tel:008657689916101) Fax:0086 576 89916009

Type of document missing	Cause
CMR Test report-Franc	Supplier do not have this report on hand, according to current ADEO quality control process, there is no need to providing.
Drinking water contact Test report-France	Supplier do not have this report on hand, according to current ADEO quality control process, there is no need to providing.
Product label-data plate- European Union(EU),France	Supplier do not have this label on product, according to current ADEO quality control process, there is no need to providing.
Safety Data Sheet-France	Supplier do not have this sheet on product, according to current ADEO quality control process, there is no need to providing.
Test report CPR-European Union(EU)	Supplier do not have this label on product, according to current ADEO quality control process, there is no need to providing.
VOC label-France	Supplier do not have this label on hand, according to current ADEO quality control process, there is no need to providing.
Product attestation of conformity-France	Supplier do not have this file on product, according to current ADEO quality control process, there is no need to providing.
Product risk analysis-France	Supplier do not have this file on product, according to current ADEO quality control process, there is no need to providing.