















Spare Part Picture	Current Spare Part No.	Upper Spare Part No.	Current CS Code	Current Spare Part Name	QTY/Set	Spare Part No. of Previous Season	Replaceable	Part #
	1A60P0690923		P06909	75" x 27.5"/1.90m x 70cm Toronto Airjet Plus SPA Liner	1		N	1
	1A60P0700523		P07005	AirJet Spa Heater With Wifi-EU(Gray)	1	1A60P0686222	Y	2
	1A60P0691223		P06912	75" x 27.5"/1.90m x 70cm Toronto Airjet Plus SPA Top Leatheroid Cover	1		N	3
	1A54P0412219		P04122	71" x 26"/1.80m x 66cm Inflatable Cover	1		N	4
	1A54P0099816		P6931ASS16	Inflation Hose for Monaco SPA	1	1A54P0092316	Y	5
	1A60P0534321		P05343	SPA Filter Set(Not Including Cartridge)	1	1A54P0093316	Y	6
	1A60P0534521		P05345	Chem Connect	1	1A54P0382119	Y	7
	1A54P0091116		P6575ASS16	SPA Stopper	2		N	8
	1A60P0534721		P05347	JET SPA Drain Adapter	1	1A54P0101816	Y	9

	1A54P0021719		P00217	Cover Adapter A	1	1A54P0092216	Y	10
	1A60P0532021		P05320	SPA Buckle	6	1A54P0070016	Y	11
	1A54P0411719		P04117	Filter Cartridge for SPA	1		N	12
	1A54P0263418		P61726ASS18	Deflation T-joint	1		N	13
	1A54P0263518		P61727ASS18	Deflated adapter	1		N	14
	1A60P0534621		P05346	Top Debris Screen for SPA	1	1A54P0023019	N	15
	1A60P0703223		P07032	80 x 700mm SPA durable foam for Toronto SPA	7		N	16
	1A60P0703123		P07031	80 x 700mm SPA durable foam for Toronto SPA	1		N	17
	1A60P0627922		P06279	Padded Pillow	5		N	18

	1A60P0793024		P07930	Cord for Toronto SPA	1		N	19
	1A54P0394016		P6609ASS16	SPA Pump Washer for Adaptor A	2		N	A
	1A54P0240617		P61316ASS17	Washer for Water Inlet	2		N	B
	1A54P0244217		P61569ASS17	Plastic Adapter for Water Inlet	1		N	BB
	1A60P0657421		P06574	SPA Pump Inflation Nuts(including Screws & O-ring)	1	1A54P0101914	Y	D
	1A60P0657521		P06575	SPA Pump Water Inlet/Outlet Nuts(including Screws & O-ring)	2	1A54P0101716	Y	E
	1A56P0411819		P04118	Underwater adhesive repair patch	3		N	J
	1A60P0781823		P07818	SPA repair kit	1		N	J