

	Document missing
--	------------------

Product identification			
Adeo Ref	844619,844620,844621,844622,844623,844624,844625,844626,843850,843851,843852,842753,842757,842735,842741,842743		
Product EAN	3276000592143 ,3276000592228,3276000592211,3276000592204 ,3276000592198 ,3276000592181,3276000592174 ,3276000592167 ,3276000592150 ,3276000596516,3276000596547,3276000596530,3276000632368,3276000632320,3276000632498,3276000632467,3276000632450		
Supplier ref	60255.002CR,60255.003CR,92647.001CR,92650.001NB,92233.001MB,92233.001BB,92233.001CR,9112.002CR,92318.002CR,92647.081CR,92233.081MB,92233.081CR,92318.011CR,9113.011CR,92233.011BB,92647.011CR,92233.011CR		

Template version history			
Version	Status	Date Status	Comments

Object

In case of supplier cannot provide related documents on time, or the document is not necessary to provide as confirmed by ADEO QM, supplier could use the missing documents template to replace required document.

Name and address of Supplier

NINGBO AOLEISHI SANITARY WARE CO.,LTD

Type of document missing	Cause
CMR Test report-France	
Drinking water contact Test report - France	It's not the drinking water faucet
Product label - data plate - European Union (EU), France	No need the product label
Safety Data Sheet - France	
VOC Label - France	
Product risk analysis - France	
Instructions manual(s) - Ukraine	No special IM for Ukraine,it's same as the ADEO one
Product label - data plate - Ukraine	
Product technical data sheet - Ukraine	
UA Test report - Ukraine	
Traceability Sheet - Ukraine	